

12/02/2021

TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM
FEDERAL REGISTER REPORT FOR 12/03/2021

UNSUITABLE PROPERTIES

BUILDING

IDAHO

5817 Toilet: Coolwater

See Directions

Lowell ID

Landholding Agency: USDA-FS

Property Number: 13202140009

Status: Excess

Directions:

latitude 36.14869800, longitude -115.504575500, Forest Road 317 Coolwater Range.

Comments:

Offsite removal only. 40-yr-old, 30 SF wood vault toilet. Poor condition-not structurally sound. Remote location in National Forest.

Reasons:

Structural Damage - Extensive Deterioration

Bldg. 5094 Tukaytespe Toilet

See Directions

Kooskia ID

Landholding Agency: USDA-FS

Property Number: 13202140010

Status: Excess

Directions:

Two miles east of Kooskia, ID, HWY 12

Comments:

Offsite removal only. 28-yr-old, 75 SF concrete vault toilet. Located in remote area.

Reasons:

Other - Vault toilet

UNSUITABLE PROPERTIES
BUILDING
IDAHO

Toilet: Meadow Creek

See Directions

Grangeville ID

Landholding Agency: USDA-FS

Property Number: 13202140011

Status: Excess

Directions:

Latitude 45.83112, longitude -115.92697. Mile marker 15 on Idaho State HWY. 14, approximately 11 miles east of Grangeville, ID

Comments:

Offsite removal only. 31-yr-old, 32 SF concrete toilet. Poor condition-structurally unsound.

Reasons:

Structural Damage - Extensive Deterioration

North Fork Slate Creek

See Directions

Slate Creek ID

Landholding Agency: USDA-FS

Property Number: 13202140012

Status: Excess

Directions:

Latitude 45.63950900, Longitude -116.1201190. 8 miles East of Slate Creek on Forest Road 354.

Comments:

Offsite removal only. 40-yr-old, 40 SF wood toilet on cement foundation. Poor condition-structurally unsound.

Reasons:

Structural Damage - Extensive Deterioration

UNSUITABLE PROPERTIES
BUILDING
OREGON

Amelia Creek Trail Head Toilet

See Directions

Unity OR 97884

Landholding Agency: USDA-FS

Property Number: 13202140013

Status: Excess

Directions:

RPUID: 2404.005421. Approximately 14 road miles (55 min drive) SW of Unity,
OR on Forest Service Road 6010.

Comments:

Offsite removal only. 30-yr-old, 20 SF, Pit Toilet (outhouse) located in remote
location inaccessible in winter or spring. Very poor condition, not structurally
sound.

Reasons:

Inaccessible. Structural Damage - Extensive Deterioration